

Essex County Fire & Rescue Service

Extract Copy of Fire Report

Details At Call

Incident Number:	
Time of Call:	/2017 10:33:34 PM
Incident Type at Control:	Fire - Building
Late Call:	No
Station Groud of Incident:	Shoeburyness
Time of Stop Message:	/2017 11:25:13 PM
Time Incident Closed:	/2017 1:05:05 AM

Details At Attendance

Incident Type:	Fire
Property Type:	Property/Building/Dwelling/House - single occupancy
Persons Rescued, Extricated, or Killed:	Yes
Persons Evacuated:	No
Pumping Appliances Deployed Before Mobilising Stopped:	2

Incident Location

Building Name / Number:	
Street:	
Town:	
Post Code:	



Essex County Fire & Rescue Service

Extract Copy of Fire Report

Additional Information

No
Under 5 minutes
Immediately
Person
No
No
Yes
Yes - occupied
Accidental
No

Action

Delay in Commencing Fire Fightin Actions:	No delay
Main Action Taken by Publich Prior to Arrival:	None
Main Action Taken by FRS Personnel:	Hosereel (high pressure) (HRJ) - tank supply only
Manual Systems Used:	No
Active Safety Systems Present:	No



Essex County Fire & Rescue Service

Extract Copy of Fire Report

Damage	
Cause of the Fire:	FAULTY ELECTRIC BLANKET
Make and Model:	N/K
Source of Ignition:	ELECTRIC BLANKET
Ignition Powered by:	Electric
First Item Ignited:	ELECTRIC WIRING
Item Mainly Responsible for Spread:	Clothing/Textiles - Bedding
Rapid Fire Growth Cause:	No rapid fire growth
Dangerous Substances Involved:	None
Explosion Involved:	No
Location of Origin:	Bedroom
Household Occupancy Type:	Lone person over pensionable age
Contributing Human Factors:	None
Was Impairment due to Suspected Drugs/Alcohol a Contributory Factor in the Fire:	No
Special Method of Building Construction:	None
Only Heat and Smoke Damage:	Yes
Fire Damaged Area at Stop:	6 - 10
TotalDamaged Area at Stop:	21 - 50

Signed:

Ana M Tuckwell | Information Governance Manager & Deputy DPO Systems and Data Department

Date: 23/02/2023