

Extract Copy of Fire Report

Details At Call

219112470
11/8/2019 1:50:35 AM

Fire - Vehicle small
No
Waltham Abbey
11/8/2019 2:34:04 AM
11/8/2019 2:46:31 AM

Details At Attendance

Incident Type:	Fire
Property Type:	Property/Road Vehicle/Car
Persons Rescued, Extricated, or Killed:	No
Persons Evacuated:	No
Pumping Appliances Deployed Before Mobilising Stopped:	1

Incident Location

Building Name / Number:	GREENWICH WAY
Street:	GREENWICH WAY
Town:	WALTHAM ABBEY
Post Code:	

Fire Multiple Seated:	No
Ignition to Discovery Time:	Under 5 minutes
Discovery to First Call Time:	Immediately
How was the Fire Discovered:	Person
Do Fire Regulations Apply:	No
Cause/Motive:	Accidental or Deliberate are both possibilities
Hazmats Involved:	No



Extract Copy of Fire Report

Action	
Delay in Commencing Fire Fighting Actions:	No delay
Main Action Taken by Public Prior to Arrival:	None
Main Action Taken by FRS Personnel:	Hosereel (high pressure) (HRJ) - tank supply only
Manual Systems Used:	No

Damage	
Cause of the Fire:	Overheating, unknown cause
Source of Ignition:	Vehicles only - Unknown
Ignition Powered by:	Not Known
First Item Ignited:	Structural/Fixtures/Fittings - Internal - Internal fittings
Item Mainly Responsible for Spread:	Structural/Fixtures/Fittings - Internal - Internal fittings
Rapid Fire Growth Cause:	No rapid fire growth
Dangerous Substances Involved:	None
Explosion Involved:	No
Location of Origin:	Engine
Contributing Human Factors:	Not known
Was Impairment due to Suspected Drugs/Alcohol a Contributory Factor in the Fire:	Don't know
Distance to Adjacent Properties Affected at Time Arrived:	1 - 5 metres
Distance to Adjacent Properties Affected at time of Stop:	1 - 5 metres

Signed:

Ana M Tuckwell | Information Governance Manager & Deputy DPO Systems and Data Department



Extract Copy of Fire Report

Details At Call

Incident Number:	219112838
Time of Call:	11/14/2019 12:51:48 AM
Incident Type at Control:	Fire - Vehicle small
Late Call:	No
Station Groud of Incident:	Waltham Abbey
Time of Stop Message:	11/14/2019 1:06:58 AM
Time Incident Closed:	11/14/2019 1:18:34 AM

Details At Attendance

Incident Type:	False Alarm
Sub Type:	False Alarm Reason/Malicious False Alarm/By phone
Property Type:	Property/Road Vehicle/Car
Persons Rescued, Extricated, or Killed:	No
Persons Evacuated:	No
Pumping Appliances Deployed Before Mobilising Stopped:	1

Incident LocationBuilding Name / Number:BRADLEY ROADStreet:BRADLEY ROADTown:WALTHAM ABBEYPost Code:Image: Comparison of the street of the street

Additional Information

Do Fire Regulations Apply:	No

Action

Damage



Extract Copy of Fire Report

Signed:

Ana M Tuckwell | Information Governance Manager & Deputy DPO Systems and Data Department



Extract Copy of Fire Report

Details At Call

Incident Number:	220123105
Time of Call:	5/19/2020 2:55:49 AM
Incident Type at Control:	Fire - Vehicle small
Late Call:	No
Station Groud of Incident:	Waltham Abbey
Time of Stop Message:	5/19/2020 3:32:25 AM
Time Incident Closed:	5/19/2020 3:39:05 AM

Details At Attendance

Incident Type:	Fire
Property Type:	Property/Road Vehicle/Car
Persons Rescued, Extricated, or Killed:	No
Persons Evacuated:	No
Pumping Appliances Deployed Before Mobilising Stopped:	1

Incident Location

Building Name / Number:	ARNOLD ROAD
Street:	Arnold Road
Town:	WALTHAM ABBEY
Post Code:	

Fire Multiple Seated:	Yes
Ignition to Discovery Time:	5 to 30 minutes
Discovery to First Call Time:	Immediately
How was the Fire Discovered:	Person
Do Fire Regulations Apply:	No
Cause/Motive:	Deliberate - others property
Hazmats Involved:	No



Extract Copy of Fire Report

Action	
Delay in Commencing Fire Fighting Actions:	No delay
Main Action Taken by Public Prior to Arrival:	None
Main Action Taken by FRS Personnel:	Hosereel (high pressure) (HRJ) - tank supply only
Manual Systems Used:	No

Damage	
Cause of the Fire:	Heat source and combustibles brought together deliberately
Source of Ignition:	Not known
Ignition Powered by:	Not applicable
First Item Ignited:	Foam, rubber, plastic - Rubber - raw material only
Item Mainly Responsible for Spread:	Explosives, gas, chemicals - Petrol/Oil products
Rapid Fire Growth Cause:	Yes, petrol/oil products
Dangerous Substances Involved:	Flammable liquids
Explosion Involved:	Don't know
Location of Origin:	Burning item placed on rear wheel
Contributing Human Factors:	Not known
Was Impairment due to Suspected Drugs/Alcohol a Contributory Factor in the Fire:	Don't know
Distance to Adjacent Properties Affected at Time Arrived:	10 - 15 metres
Distance to Adjacent Properties Affected at time of Stop:	Over 15 metres

Signed:

VD

Ana M Tuckwell | Information Governance Manager & Deputy DPO Systems and Data Department



Extract Copy of Fire Report

Details At Call

Incident Number:	21006465
Time of Call:	4/4/2010 4:01:29 AM
Origin of Call:	Person (land line)
Incident Type at Control:	Fire - Vehicle small
Late Call:	No
Station Groud of Incident:	Waltham Abbey
Station Groud of Incident: Time of Stop Message:	

Details At Attendance

Incident Type:	Fire
Property Type:	Property/Road Vehicle/Car
Persons Rescued, Extricated, or Killed:	No
Persons Evacuated:	No
Pumping Appliances Deployed Before Mobilising Stopped:	1

Incident Location

Building Name / Number:	
Street:	MAYFLOWER CL
Town:	WALTHAM ABBEY
Post Code:	

Fire Multiple Seated:	No
Ignition to Discovery Time:	Not known
Discovery to First Call Time:	Immediately
How was the Fire Discovered:	Person
Do Fire Regulations Apply:	No
Cause/Motive:	Deliberate - unknown owner
Hazmats Involved:	No



Extract Copy of Fire Report

Action	
Delay in Commencing Fire Fighting Actions:	No delay
Main Action Taken by Public Prior to Arrival:	None
Main Action Taken by FRS Personnel:	Hosereel (high pressure) (HRJ) - tank supply only
Manual Systems Used:	No

Damage	
Cause of the Fire:	Heat source and combustibles brought together deliberately
Source of Ignition:	Not known
Ignition Powered by:	Not Known
First Item Ignited:	Not known
Item Mainly Responsible for Spread:	Explosives, gas, chemicals - Petrol/Oil products
Rapid Fire Growth Cause:	No rapid fire growth
Dangerous Substances Involved:	None
Explosion Involved:	No
Location of Origin:	Driver/Passenger area
Contributing Human Factors:	Not known
Was Impairment due to Suspected Drugs/Alcohol a Contributory Factor in the Fire:	No
Distance to Adjacent Properties Affected at Time Arrived:	No other property affected
Distance to Adjacent Properties Affected at time of Stop:	No other property affected
Fire Damaged Area at Stop:	6 - 10

Signed:

Ana M Tuckwell | Information Governance Manager & Deputy DPO Systems and Data Department



Extract Copy of Fire Report

Details At Call

Incident Number:	21009743
Time of Call:	5/17/2010 6:29:40 AM
Origin of Call:	Person (mobile)
Incident Type at Control:	Fire - Road furniture
Late Call:	No
Station Groud of Incident:	Waltham Abbey
Time of Stop Message:	5/17/2010 6:46:33 AM
Time Incident Closed:	5/17/2010 7:08:31 AM

Details At Attendance

Incident Type:	Fire
Property Type:	Property/Outdoor/Outdoor structures/Post box
Persons Rescued, Extricated, or Killed:	No
Persons Evacuated:	No
Pumping Appliances Deployed Before Mobilising Stopped:	1

Incident Location

Street:	DEER PARK WAY
Town:	WALTHAM ABBEY
Post Code:	

Fire Multiple Seated:	No
Ignition to Discovery Time:	Over 2 hours
Discovery to First Call Time:	Under 5 minutes
How was the Fire Discovered:	Person
Do Fire Regulations Apply:	No
Cause/Motive:	Deliberate - others property
Hazmats Involved:	No



Extract Copy of Fire Report

Action	
Delay in Commencing Fire Fighting Actions:	No delay
Main Action Taken by Public Prior to Arrival:	None
Main Action Taken by FRS Personnel:	Dry powder (DP)
Manual Systems Used:	No

Damage	
Cause of the Fire:	Heat source and combustibles brought together deliberately
Source of Ignition:	Not known
Ignition Powered by:	Not Known
First Item Ignited:	Not known
Item Mainly Responsible for Spread:	Paper/Cardboard -
Rapid Fire Growth Cause:	No rapid fire growth
Dangerous Substances Involved:	None
Explosion Involved:	No
Contributing Human Factors:	Deliberate
Was Impairment due to Suspected Drugs/Alcohol a Contributory Factor in the Fire:	Don't know

Signed:

Ana M Tuckwell | Information Governance Manager & Deputy DPO Systems and Data Department



Extract Copy of Fire Report

Details At Call

Incident Number:	21012300
Time of Call:	6/19/2010 12:57:07 AM
Origin of Call:	FRS
Incident Type at Control:	Fire - Fire in the open - small
Late Call:	No
Station Groud of Incident:	Waltham Abbey
Time of Stop Message:	6/19/2010 1:14:44 AM
Time Incident Closed:	6/19/2010 1:43:53 AM

Details At Attendance

Incident Type:	Fire
Property Type:	Property/Road Vehicle/Van
Persons Rescued, Extricated, or Killed:	No
Persons Evacuated:	No
Pumping Appliances Deployed Before Mobilising Stopped:	1

Incident Location

Building Name / Number:	;
Street:	BRADLEY RD
Town:	WALTHAM ABBEY
Post Code:	

Fire Multiple Seated:	No
Ignition to Discovery Time:	Under 5 minutes
Discovery to First Call Time:	Immediately
How was the Fire Discovered:	Person
Do Fire Regulations Apply:	No
Cause/Motive:	Deliberate - own property
Hazmats Involved:	No



Extract Copy of Fire Report

Action	
Delay in Commencing Fire Fighting Actions:	Delay due to: Vehicle access problems
Main Action Taken by Public Prior to Arrival:	None
Main Action Taken by FRS Personnel:	Hosereel (high pressure) (HRJ) - augmented supply
Manual Systems Used:	No

Damage	
Cause of the Fire:	Heat source and combustibles brought together deliberately
Source of Ignition:	Not known
Ignition Powered by:	Not Known
First Item Ignited:	Not known
Item Mainly Responsible for Spread:	Foam, rubber, plastic - Rubber - raw material only
Rapid Fire Growth Cause:	No rapid fire growth
Dangerous Substances Involved:	None
Explosion Involved:	No
Location of Origin:	Driver/Passenger area
Contributing Human Factors:	Deliberate igntion
Was Impairment due to Suspected Drugs/Alcohol a Contributory Factor in the Fire:	Don't know
Distance to Adjacent Properties Affected at Time Arrived:	No other property affected
Distance to Adjacent Properties Affected at time of Stop:	No other property affected
Fire Damaged Area at Stop:	Up to 5

Signed:

. . . .

Ana M Tuckwell | Information Governance Manager & Deputy DPO Systems and Data Department



Extract Copy of Fire Report

Details At Call

Incident Number:	21208264
Time of Call:	5/3/2012 7:37:09 AM
Origin of Call:	Person (land line)
Incident Type at Control:	Fire - Building
Late Call:	No
Station Groud of Incident:	Waltham Abbey
Time of Stop Message:	5/3/2012 7:53:33 AM
Time Incident Closed:	5/3/2012 8:28:12 AM

Details At Attendance

Incident Type:	Fire
Property Type:	Property/Building/Non Residential/Private garage
Persons Rescued, Extricated, or Killed:	No
Persons Evacuated:	No
Pumping Appliances Deployed Before Mobilising Stopped:	2

Incident Location	
Building Name / Number:	
Street:	FOXWOOD CHASE
Town:	WALTHAM ABBEY
Post Code:	



Extract Copy of Fire Report

Additional Information

٧o
Not known
mmediately
Person
lo
lo
lo
Not known
Accidental
lo

Action

Delay in Commencing Fire Fighting Actions:	No delay
Main Action Taken by Public Prior to Arrival:	Fire extinguisher
Main Action Taken by FRS Personnel:	Hosereel (high pressure) (HRJ) - tank supply only
Manual Systems Used:	No
Active Safety Systems Present:	No



Extract Copy of Fire Report

Damage	
Cause of the Fire:	Fault in equipment or appliance
Make and Model:	UNKOWN
Source of Ignition:	Not known
Ignition Powered by:	Electric
First Item Ignited:	Not known
Item Mainly Responsible for Spread:	Not known
Rapid Fire Growth Cause:	No rapid fire growth
Dangerous Substances Involved:	None
Explosion Involved:	No
Location of Origin:	Garage
Contributing Human Factors:	None
Was Impairment due to Suspected Drugs/Alcohol a Contributory Factor in the Fire:	No
Special Method of Building Construction:	None
Only Heat and Smoke Damage:	No
Distance to Adjacent Properties Affected at Time Arrived:	No other property affected
Distance to Adjacent Properties Affected at time of Stop:	No other property affected
Fire Damaged Area at Stop:	Up to 5
TotalDamaged Area at Stop:	Up to 5

Signed:

-

Ana M Tuckwell | Information Governance Manager & Deputy DPO Systems and Data Department



Extract Copy of Fire Report

Details At Call

Incident Number:	21603865
Time of Call:	3/16/2016 6:30:40 PM
Origin of Call:	FRS
Incident Type at Control:	Fire - Vehicle small
Late Call:	No
Late Call: Station Groud of Incident:	No Waltham Abbey

Details At Attendance

Incident Type:	Fire
Property Type:	Property/Road Vehicle/Multiple Vehicles
Persons Rescued, Extricated, or Killed:	No
Persons Evacuated:	No
Pumping Appliances Deployed Before Mobilising Stopped:	1

Incident Location

Building Name / Number:	car park
Street:	GREENWICH WAY
Town:	WALTHAM ABBEY
Post Code:	

Fire Multiple Seated:	No
Ignition to Discovery Time:	Immediately
Discovery to First Call Time:	Immediately
How was the Fire Discovered:	Person
Do Fire Regulations Apply:	No
Cause/Motive:	Accidental
Hazmats Involved:	No



Extract Copy of Fire Report

Action	
Delay in Commencing Fire Fighting Actions:	No delay
Main Action Taken by Public Prior to Arrival:	None
Main Action Taken by FRS Personnel:	Hosereel (high pressure) (HRJ) - tank supply only
Manual Systems Used:	No

Damage	
Cause of the Fire:	faulty vehicle heater
Make and Model:	renault scenic
Source of Ignition:	Vehicles only - Electrical fault
Ignition Powered by:	Electric
First Item Ignited:	Explosives, gas, chemicals - Petrol/Oil products
Item Mainly Responsible for Spread:	Foam, rubber, plastic - Plastic - raw material only
Rapid Fire Growth Cause:	No rapid fire growth
Dangerous Substances Involved:	None
Explosion Involved:	No
Location of Origin:	Driver/Passenger area
Contributing Human Factors:	None
Was Impairment due to Suspected Drugs/Alcohol a Contributory Factor in the Fire:	No
Distance to Adjacent Properties Affected at Time Arrived:	1 - 5 metres
Distance to Adjacent Properties Affected at time of Stop:	1 - 5 metres

Signed:

Ana M Tuckwell | Information Governance Manager & Deputy DPO Systems and Data Department



Extract Copy of Fire Report

Details At Call

Incident Number:	21754619
Time of Call:	5/16/2017 3:19:59 PM
Incident Type at Control:	Fire - Fire in the open - large
Late Call:	No
Station Groud of Incident:	Waltham Abbey
Time of Stop Message:	5/23/2017 5:00:05 PM
Time Incident Closed:	5/24/2017 2:18:23 AM

Details At Attendance

Incident Type:	Fire
Property Type:	Property/Outdoor/Other outdoors (including land)/Loose refuse (incl in garden)
Persons Rescued, Extricated, or Killed:	No
Persons Evacuated:	No
Pumping Appliances Deployed Before Mobilising Stopped:	42

Incident Location

Building Name / Number:	HOE LANE
Street:	HOE LANE
Town:	WALTHAM ABBEY
Post Code:	

Fire Multiple Seated:	No
Ignition to Discovery Time:	5 to 30 minutes
Discovery to First Call Time:	5 to 30 minutes
How was the Fire Discovered:	Person
Do Fire Regulations Apply:	No
Cause/Motive:	Accidental or Deliberate are both possibilities
Hazmats Involved:	No



Extract Copy of Fire Report

Action	
Delay in Commencing Fire Fighting Actions:	No delay
Main Action Taken by Public Prior to Arrival:	None
Main Action Taken by FRS Personnel:	Main branch/Jet (J)
Manual Systems Used:	No

Damage	
Cause of the Fire:	Combustible articles too close to heat source (or fire)
Source of Ignition:	Not known
Ignition Powered by:	Not Known
First Item Ignited:	Rubbish/Waste/Recycling - Recycling -
Item Mainly Responsible for Spread:	Rubbish/Waste/Recycling - Recycling -
Rapid Fire Growth Cause:	No rapid fire growth
Dangerous Substances Involved:	None
Explosion Involved:	No
Location of Origin:	In open area next to housing
Contributing Human Factors:	None
Was Impairment due to Suspected Drugs/Alcohol a Contributory Factor in the Fire:	No

Signed:

Ana M Tuckwell | Information Governance Manager & Deputy DPO Systems and Data Department



Extract Copy of Fire Report

Details At Call

21764128
10/5/2017 3:47:14 AM
Fire - Building
No
Waltham Abbey
10/5/2017 4:07:24 AM
10/5/2017 4:19:03 AM

Details At Attendance

Incident Type:	False Alarm
Sub Type:	False Alarm Reason/Malicious False Alarm/By phone
Property Type:	Property/Building/Dwelling/House - single occupancy
Persons Rescued, Extricated, or Killed:	No
Persons Evacuated:	No
Pumping Appliances Deployed Before Mobilising Stopped:	2

Incident Location

Building Name / Number:	
Street:	BRADLEY ROAD
Town:	WALTHAM ABBEY
Post Code:	

Additional Information

Do Fire Regulations Apply:	No

Action

Damage



Extract Copy of Fire Report

Signed:

Ana M Tuckwell | Information Governance Manager & Deputy DPO Systems and Data Department



Extract Copy of Fire Report

Details At Call

Incident Number:	21882558
Time of Call:	7/23/2018 2:12:18 PM
Incident Type at Control:	Fire - Building
Late Call:	No
Station Groud of Incident:	Waltham Abbey
Time of Stop Message:	7/23/2018 2:38:06 PM
Time Incident Closed:	7/23/2018 2:40:10 PM

Details At Attendance

Incident Type:	Fire
Property Type:	Property/Outdoor/Grassland, woodland and crops/Scrub land
Persons Rescued, Extricated, or Killed:	No
Persons Evacuated:	No
Pumping Appliances Deployed Before Mobilising Stopped:	1

Incident Location

Building Name / Number:	MERIDIAN WAY
Town:	WALTHAM ABBEY
Post Code:	

Additional Information

Do Fire Regulations Apply:	No
Cause/Motive:	Accidental or Deliberate are both possibilities
Estimated Fire Damage:	51 - 100
Hazmats Involved:	No

Action



Extract Copy of Fire Report

Signed:

Ana M Tuckwell | Information Governance Manager & Deputy DPO Systems and Data Department



Extract Copy of Fire Report

Details At Call

Incident Number:	21885355
Time of Call:	8/30/2018 3:39:47 AM
Incident Type at Control:	Fire - Vehicle small
Late Call:	No
Station Groud of Incident:	Waltham Abbey
Time of Stop Message:	8/30/2018 3:56:04 AM
Time Incident Closed:	8/30/2018 3:56:36 AM

Details At Attendance

Incident Type:	False Alarm
Sub Type:	False Alarm Reason/Malicious False Alarm/By phone
Property Type:	Property/Road Vehicle/Car
Persons Rescued, Extricated, or Killed:	No
Persons Evacuated:	No
Pumping Appliances Deployed Before Mobilising Stopped:	1

Incident Location Building Name / Number: BRADLEY ROAD Town: WALTHAM ABBEY Post Code: Image: Code State State

Additional Information Do Fire Regulations Apply: No

Action

Damage



Extract Copy of Fire Report

Signed:

Ana M Tuckwell | Information Governance Manager & Deputy DPO Systems and Data Department



Extract Copy of Fire Report

Details At Call

Incident Number:	219102613
Time of Call:	6/18/2019 9:05:59 PM
Incident Type at Control:	Fire - Building
Late Call:	No
Station Groud of Incident:	
	Waltham Abbey
Time of Stop Message:	6/18/2019 9:18:52 PM
Time Incident Closed:	6/18/2019 9:35:16 PM

Details At Attendance

Incident Type:	Fire
Property Type:	Property/Outdoor/Outdoor structures/Wheelie Bin
Persons Rescued, Extricated, or Killed:	No
Persons Evacuated:	No
Pumping Appliances Deployed Before Mobilising Stopped:	1

Incident Location

Building Name / Number:	HOWARD CLOSE
Town:	WALTHAM ABBEY
Post Code:	

Additional Information

Do Fire Regulations Apply:	No
Cause/Motive:	Deliberate - unknown owner
Estimated Fire Damage:	Up to 5
Hazmats Involved:	No

Action

Damage



Extract Copy of Fire Report

Signed:

Ana M Tuckwell | Information Governance Manager & Deputy DPO Systems and Data Department



Extract Copy of Fire Report

Details At Call

Incident Number:	219107043
Time of Call:	8/20/2019 5:51:39 AM
Origin of Call:	Person (mobile)
Incident Type at Control:	Fire - Vehicle small
Late Call:	No
Station Groud of Incident:	Waltham Abbey
Time of Stop Message:	8/20/2019 6:19:50 AM
Time Incident Closed:	8/20/2019 6:37:41 AM

Details At Attendance

Incident Type:	Fire
Property Type:	Property/Road Vehicle/Car
Persons Rescued, Extricated, or Killed:	No
Persons Evacuated:	No
Pumping Appliances Deployed Before Mobilising Stopped:	1

Incident Location

Building Name / Number:	BRADLEY ROAD
Street:	BRADLEY ROAD
Town:	WALTHAM ABBEY
Post Code:	

Fire Multiple Seated:	No
Ignition to Discovery Time:	5 to 30 minutes
Discovery to First Call Time:	Immediately
How was the Fire Discovered:	Person
Do Fire Regulations Apply:	No
Cause/Motive:	Accidental
Hazmats Involved:	No



Extract Copy of Fire Report

Action	
Delay in Commencing Fire Fighting Actions:	No delay
Main Action Taken by Public Prior to Arrival:	None
Main Action Taken by FRS Personnel:	Hosereel (high pressure) (HRJ) - tank supply only
Manual Systems Used:	No

Damage	
Cause of the Fire:	Faulty leads to equipment or appliance
Make and Model:	VW polo
Source of Ignition:	Vehicles only - Electrical fault
Ignition Powered by:	Electric
First Item Ignited:	Structural/Fixtures/Fittings - Internal - Wiring insulation
Item Mainly Responsible for Spread:	Foam, rubber, plastic - Plastic - raw material only
Rapid Fire Growth Cause:	No rapid fire growth
Dangerous Substances Involved:	None
Explosion Involved:	No
Location of Origin:	Engine
Contributing Human Factors:	None
Was Impairment due to Suspected Drugs/Alcohol a Contributory Factor in the Fire:	No
Distance to Adjacent Properties Affected at Time Arrived:	1 - 5 metres
Distance to Adjacent Properties Affected at time of Stop:	1 - 5 metres

Signed:

Ana M Tuckwell | Information Governance Manager & Deputy DPO Systems and Data Department



Extract Copy of Fire Report

Details At Call

Incident Number:	219108599
Time of Call:	9/9/2019 3:07:31 AM
Incident Type at Control:	Fire - Vehicle small
Late Call:	No
Station Groud of Incident:	Waltham Abbey
Time of Stop Message:	9/9/2019 3:37:08 AM
Time Incident Closed:	9/9/2019 4:15:58 AM

Details At Attendance

Incident Type:	Fire
Property Type:	Property/Road Vehicle/Car
Persons Rescued, Extricated, or Killed:	No
Persons Evacuated:	No
Pumping Appliances Deployed Before Mobilising Stopped:	1

Incident Location

Building Name / Number:	ARNOLD ROAD
Town:	WALTHAM ABBEY
Post Code:	

Additional InformationFire Multiple Seated:NoIgnition to Discovery Time:Under 5 minutesDiscovery to First Call Time:ImmediatelyHow was the Fire Discovered:PersonDo Fire Regulations Apply:NoCause/Motive:Accidental or Deliberate are both possibilitiesHazmats Involved:No



Extract Copy of Fire Report

Action	
Delay in Commencing Fire Fighting Actions:	No delay
Main Action Taken by Public Prior to Arrival:	None
Main Action Taken by FRS Personnel:	Hosereel (high pressure) (HRJ) - tank supply only
Manual Systems Used:	No

Damage	
Cause of the Fire:	Unknown
Make and Model:	mercedes A class
Source of Ignition:	Not known
Ignition Powered by:	Not Known
First Item Ignited:	Structural/Fixtures/Fittings - External - External fittings
Item Mainly Responsible for Spread:	Structural/Fixtures/Fittings - External - External fittings
Rapid Fire Growth Cause:	No rapid fire growth
Dangerous Substances Involved:	None
Explosion Involved:	No
Location of Origin:	Rear light cluster back wheel
Contributing Human Factors:	Not known
Was Impairment due to Suspected Drugs/Alcohol a Contributory Factor in the Fire:	Don't know
Distance to Adjacent Properties Affected at Time Arrived:	1 - 5 metres
Distance to Adjacent Properties Affected at time of Stop:	1 - 5 metres

Signed:

V

Ana M Tuckwell | Information Governance Manager & Deputy DPO Systems and Data Department



Extract Copy of Fire Report

Details At Call

Incident Number:	219112376
Time of Call:	11/6/2019 4:59:43 AM
Incident Type at Control:	Fire - Vehicle small
Late Call:	No
Station Groud of Incident:	Waltham Abbey
Time of Stop Message:	11/6/2019 5:21:28 AM
Time Incident Closed:	11/6/2019 5:47:49 AM

Details At Attendance

Incident Type:	Fire
Property Type:	Property/Road Vehicle/Car
Persons Rescued, Extricated, or Killed:	No
Persons Evacuated:	No
Pumping Appliances Deployed Before Mobilising Stopped:	1

Incident Location

Building Name / Number:	BRADLEY ROAD
Street:	Bradley road
Town:	WALTHAM ABBEY
Post Code:	

Fire Multiple Seated:	No
Ignition to Discovery Time:	Not known
Discovery to First Call Time:	Immediately
How was the Fire Discovered:	Person
Do Fire Regulations Apply:	No
Cause/Motive:	Accidental or Deliberate are both possibilities
Hazmats Involved:	No



Extract Copy of Fire Report

Action	
Delay in Commencing Fire Fighting Actions:	No delay
Main Action Taken by Public Prior to Arrival:	None
Main Action Taken by FRS Personnel:	Hosereel (high pressure) (HRJ) - tank supply only
Manual Systems Used:	No

Damage	
Cause of the Fire:	Accumulation of flammable material
Source of Ignition:	Fuel/Chemical related - Liquids; petrol/oil related
Ignition Powered by:	Not applicable
First Item Ignited:	Structural/Fixtures/Fittings - Internal - Internal fittings
Item Mainly Responsible for Spread:	Foam, rubber, plastic - Plastic - raw material only
Rapid Fire Growth Cause:	Yes, petrol/oil products
Dangerous Substances Involved:	Flammable liquids
Explosion Involved:	Don't know
Location of Origin:	Driver/Passenger area
Contributing Human Factors:	Not known
Was Impairment due to Suspected Drugs/Alcohol a Contributory Factor in the Fire:	Don't know
Distance to Adjacent Properties Affected at Time Arrived:	No other property affected
Distance to Adjacent Properties Affected at time of Stop:	No other property affected

Signed:

Ana M Tuckwell | Information Governance Manager & Deputy DPO Systems and Data Department



Extract Copy of Fire Report

Details At Call

Incident Number:	220118794
Time of Call:	2/27/2020 11:16:58 PM
Incident Type at Control:	Fire - Vehicle small
Late Call:	No
Station Groud of Incident:	Waltham Abbey
Time of Stop Message:	2/28/2020 12:25:54 AM
Time Incident Closed:	2/28/2020 4:07:03 PM

Details At Attendance

Incident Type:	Fire
Property Type:	Property/Road Vehicle/Van
Persons Rescued, Extricated, or Killed:	No
Persons Evacuated:	No
Pumping Appliances Deployed Before Mobilising Stopped:	1

Incident Location

Building Name / Number:	BRADLEY ROAD
Street:	BRADLEY ROAD
Town:	WALTHAM ABBEY
Post Code:	

Fire Multiple Seated:	No
Ignition to Discovery Time:	Under 5 minutes
Discovery to First Call Time:	Immediately
How was the Fire Discovered:	Person
Do Fire Regulations Apply:	No
Cause/Motive:	Deliberate - others property
Hazmats Involved:	No



Extract Copy of Fire Report

Action	
Delay in Commencing Fire Fighting Actions:	No delay
Main Action Taken by Public Prior to Arrival:	None
Main Action Taken by FRS Personnel:	Hosereel (high pressure) (HRJ) - tank supply only
Manual Systems Used:	No

Damage	
Cause of the Fire:	Heat source and combustibles brought together deliberately
Source of Ignition:	Naked flame - Lighted paper or card, or naked flame
Ignition Powered by:	Not applicable
First Item Ignited:	Structural/Fixtures/Fittings - External - External fittings
Item Mainly Responsible for Spread:	Structural/Fixtures/Fittings - Internal - Internal fittings
Rapid Fire Growth Cause:	Yes, petrol/oil products
Dangerous Substances Involved:	None
Explosion Involved:	No
Location of Origin:	Engine
Contributing Human Factors:	None
Was Impairment due to Suspected Drugs/Alcohol a Contributory Factor in the Fire:	Don't know
Distance to Adjacent Properties Affected at Time Arrived:	No other property affected
Distance to Adjacent Properties Affected at time of Stop:	No other property affected

Signed:

VD

Ana M Tuckwell | Information Governance Manager & Deputy DPO Systems and Data Department



Extract Copy of Fire Report

Details At Call

Incident Number:	220123360
Time of Call:	5/23/2020 2:42:47 AM
Incident Type at Control:	Fire - Vehicle small
Late Call:	No
Station Groud of Incident:	Waltham Abbey
Time of Stop Message:	5/23/2020 3:26:12 AM
Time Incident Closed:	5/23/2020 8:36:28 AM

Details At Attendance

Incident Type:	Fire
Property Type:	Property/Road Vehicle/Multiple Vehicles
Persons Rescued, Extricated, or Killed:	No
Persons Evacuated:	No
Pumping Appliances Deployed Before Mobilising Stopped:	1

Incident Location

Building Name / Number:	MERIDIAN PARK
Street:	MERIDIAN WAY
Town:	WALTHAM ABBEY
Post Code:	

Fire Multiple Seated:	Yes
Ignition to Discovery Time:	5 to 30 minutes
Discovery to First Call Time:	Immediately
How was the Fire Discovered:	Person
Do Fire Regulations Apply:	No
Cause/Motive:	Deliberate - others property
Hazmats Involved:	No



Extract Copy of Fire Report

Action	
Delay in Commencing Fire Fighting Actions:	No delay
Main Action Taken by Public Prior to Arrival:	None
Main Action Taken by FRS Personnel:	Hosereel (high pressure) (HRJ) - augmented supply
Manual Systems Used:	No

Damage	
Cause of the Fire:	Heat source and combustibles brought together deliberately
Source of Ignition:	Fuel/Chemical related - Liquids; petrol/oil related
Ignition Powered by:	Not applicable
First Item Ignited:	Foam, rubber, plastic - Rubber - raw material only
Item Mainly Responsible for Spread:	Foam, rubber, plastic - Plastic - raw material only
Rapid Fire Growth Cause:	Yes, strong wind
Dangerous Substances Involved:	None
Explosion Involved:	No
Location of Origin:	object/rag set on fire on rear tyre
Contributing Human Factors:	Not known
Was Impairment due to Suspected Drugs/Alcohol a Contributory Factor in the Fire:	Don't know
Distance to Adjacent Properties Affected at Time Arrived:	1 - 5 metres
Distance to Adjacent Properties Affected at time of Stop:	1 - 5 metres

Signed:

VD

Ana M Tuckwell | Information Governance Manager & Deputy DPO Systems and Data Department



Extract Copy of Fire Report

Details At Call

Incident Number:	220123616
Time of Call:	5/26/2020 6:37:21 PM
Incident Type at Control:	Fire - Building
Late Call:	No
Station Groud of Incident:	Waltham Abbey
Time of Stop Message:	5/26/2020 6:54:32 PM
Time Incident Closed:	5/26/2020 7:05:48 PM

Details At Attendance

Incident Type:	Fire
Property Type:	Property/Outdoor/Outdoor structures/Wheelie Bin
Persons Rescued, Extricated, or Killed:	No
Persons Evacuated:	No
Pumping Appliances Deployed Before Mobilising Stopped:	2

Incident Location

Building Name / Number:	
Street:	FOXWOOD CHASE
Town:	WALTHAM ABBEY
Post Code:	

Do Fire Regulations Apply:	No
Cause/Motive:	Accidental or Deliberate are both possibilities
Estimated Fire Damage:	Up to 5
Hazmats Involved:	No



Extract Copy of Fire Report

Damage

Signed:

Ana M Tuckwell | Information Governance Manager & Deputy DPO Systems and Data Department



Extract Copy of Fire Report

Details At Call

Incident Number:	220124991
Time of Call:	6/18/2020 3:14:09 AM
Origin of Call:	Person (mobile)
Incident Type at Control:	Fire - Vehicle small
Late Call:	No
Station Groud of Incident:	Waltham Abbey
Time of Stop Message:	6/18/2020 3:53:08 AM

Details At Attendance

Incident Type:	Fire
Property Type:	Property/Road Vehicle/Car
Persons Rescued, Extricated, or Killed:	No
Persons Evacuated:	No
Pumping Appliances Deployed Before Mobilising Stopped:	1

Incident Location

Building Name / Number:	QUEEN MARYS COURT
Street:	HARRISON ROAD
Town:	WALTHAM ABBEY
Post Code:	

Fire Multiple Seated:	No
Ignition to Discovery Time:	Under 5 minutes
Discovery to First Call Time:	Immediately
How was the Fire Discovered:	Person
Do Fire Regulations Apply:	No
Cause/Motive:	Deliberate - others property
Hazmats Involved:	No



Extract Copy of Fire Report

Action	
Delay in Commencing Fire Fighting Actions:	No delay
Main Action Taken by Public Prior to Arrival:	None
Main Action Taken by FRS Personnel:	Hosereel (high pressure) (HRJ) - tank supply only
Manual Systems Used:	No

Damage	
Cause of the Fire:	Heat source and combustibles brought together deliberately
Source of Ignition:	Fuel/Chemical related - Liquids; petrol/oil related
Ignition Powered by:	Not applicable
First Item Ignited:	Structural/Fixtures/Fittings - External -
Item Mainly Responsible for Spread:	Structural/Fixtures/Fittings - External - External fittings
Rapid Fire Growth Cause:	No rapid fire growth
Dangerous Substances Involved:	Flammable liquids
Explosion Involved:	No
Location of Origin:	Wheels/Brakes
Contributing Human Factors:	Not known
Was Impairment due to Suspected Drugs/Alcohol a Contributory Factor in the Fire:	Don't know
Distance to Adjacent Properties Affected at Time Arrived:	No other property affected
Distance to Adjacent Properties Affected at time of Stop:	No other property affected

Signed:

Ana M Tuckwell | Information Governance Manager & Deputy DPO Systems and Data Department



Extract Copy of Fire Report

Details At Call

Incident Number:	220124994
Time of Call:	6/18/2020 4:11:48 AM
Incident Type at Control:	Fire - Vehicle small
Late Call:	No
Station Groud of Incident:	Waltham Abbey
Time of Stop Message:	6/18/2020 4:30:46 AM
Time Incident Closed:	6/18/2020 1:36:18 PM

Details At Attendance

Incident Type:	Fire
Property Type:	Property/Road Vehicle/Car
Persons Rescued, Extricated, or Killed:	No
Persons Evacuated:	No
Pumping Appliances Deployed Before Mobilising Stopped:	1

Incident Location

Building Name / Number:	STREET RECORD BRADLEY ROAD
Street:	BRADLEY ROAD
Town:	WALTHAM ABBEY
Post Code:	

Fire Multiple Seated:	No
Ignition to Discovery Time:	Under 5 minutes
Discovery to First Call Time:	Immediately
How was the Fire Discovered:	Person
Do Fire Regulations Apply:	No
Cause/Motive:	Deliberate - others property
Hazmats Involved:	No



Extract Copy of Fire Report

Action	
Delay in Commencing Fire Fighting Actions:	No delay
Main Action Taken by Public Prior to Arrival:	None
Main Action Taken by FRS Personnel:	Hosereel (high pressure) (HRJ) - tank supply only
Manual Systems Used:	No

Damage	
Cause of the Fire:	Heat source and combustibles brought together deliberately
Source of Ignition:	Fuel/Chemical related - Liquids; petrol/oil related
Ignition Powered by:	Not applicable
First Item Ignited:	Structural/Fixtures/Fittings - External - External fittings
Item Mainly Responsible for Spread:	Foam, rubber, plastic - Rubber - raw material only
Rapid Fire Growth Cause:	No rapid fire growth
Dangerous Substances Involved:	Flammable liquids
Explosion Involved:	No
Location of Origin:	Wheels/Brakes
Contributing Human Factors:	Not known
Was Impairment due to Suspected Drugs/Alcohol a Contributory Factor in the Fire:	Don't know
Distance to Adjacent Properties Affected at Time Arrived:	1 - 5 metres
Distance to Adjacent Properties Affected at time of Stop:	5 - 10 metres

Signed:

VD

Ana M Tuckwell | Information Governance Manager & Deputy DPO Systems and Data Department



Extract Copy of Fire Report

Details At Call

Incident Number:	220125853
Time of Call:	7/1/2020 2:50:38 AM
Incident Type at Control:	Fire - Building
Late Call:	No
Station Groud of Incident:	Harlow Central
Time of Stop Message:	7/1/2020 4:40:29 AM
Time Incident Closed:	7/1/2020 1:36:52 PM

Details At Attendance

Incident Type:	Fire
Property Type:	Property/Building/Non Residential/Vehicle Repair
Persons Rescued, Extricated, or Killed:	No
Persons Evacuated:	No
Pumping Appliances Deployed Before Mobilising Stopped:	5

Incident Location

Building Name / Number:	SPANNERS GARAGE
Street:	SEDGE GREEN
Town:	HARLOW
Post Code:	



Extract Copy of Fire Report

Fire Multiple Seated:	Yes
Ignition to Discovery Time:	5 to 30 minutes
Discovery to First Call Time:	Under 5 minutes
How was the Fire Discovered:	Person
Do Fire Regulations Apply:	Yes
Means of Escape:	OK - no visible concerns
Compartmentation:	No compartmentation in building
Alarm System Present:	Don't know
Anyone in Building at Time of Fire:	No
Is the Building Normally Occupied:	Yes - occupied
Cause/Motive:	Deliberate - others property
Hazmats Involved:	No

Action

	Na dalari
Delay in Commencing Fire Fighting Actions:	No delay
Main Action Taken by Public Prior to Arrival:	None
Main Action Taken by FRS Personnel:	Main branch/Jet (J)
Manual Systems Used:	No
Building Fire Fighting Facilities Present:	No
Active Safety Systems Present:	No



Extract Copy of Fire Report

Damage	
Cause of the Fire:	Heat source and combustibles brought together deliberately
Source of Ignition:	Not known
Ignition Powered by:	Not Known
First Item Ignited:	Not known
Item Mainly Responsible for Spread:	Vehicles
Rapid Fire Growth Cause:	Yes, strong wind
Dangerous Substances Involved:	None
Explosion Involved:	No
Location of Origin:	Vehicle
Contributing Human Factors:	The fire was started deliberately
Was Impairment due to Suspected Drugs/Alcohol a Contributory Factor in the Fire:	Don't know
Special Method of Building Construction:	None
Only Heat and Smoke Damage:	No
Distance to Adjacent Properties Affected at Time Arrived:	No other property affected
Distance to Adjacent Properties Affected at time of Stop:	No other property affected
Fire Damaged Area at Stop:	51 - 100
TotalDamaged Area at Stop:	51 - 100

Signed:

Ana M Tuckwell | Information Governance Manager & Deputy DPO Systems and Data Department



Extract Copy of Fire Report

Details At Call

Incident Number:	220128475
Time of Call:	8/9/2020 8:23:24 PM
Origin of Call:	Person (mobile)
Incident Type at Control:	Fire - Vehicle small
Late Call:	No
Station Groud of Incident:	Waltham Abbey
Time of Stop Message:	8/9/2020 8:48:24 PM
Time Incident Closed:	8/9/2020 9:15:16 PM

Details At Attendance

Incident Type:	Fire
Property Type:	Property/Road Vehicle/Car
Persons Rescued, Extricated, or Killed:	No
Persons Evacuated:	No
Pumping Appliances Deployed Before Mobilising Stopped:	1

Incident Location

Building Name / Number:	WARLIES PARK ESTATE
Street:	HORSESHOE HILL
Town:	WALTHAM ABBEY
Post Code:	

Do Fire Regulations Apply:	No
Cause/Motive:	Deliberate - unknown owner
Hazmats Involved:	No



Extract Copy of Fire Report

Damage

Signed:

Ana M Tuckwell | Information Governance Manager & Deputy DPO Systems and Data Department



Extract Copy of Fire Report

Details At Call

Incident Number:	220133782
Time of Call:	11/2/2020 8:08:05 PM
Origin of Call:	Person (mobile)
Incident Type at Control:	Fire - Fire in the open - small
Late Call:	No
Station Groud of Incident:	Waltham Abbey
Time of Stop Message:	11/2/2020 8:24:08 PM
Time of Stop Message.	11/2/2020 0.24.00 F W

Details At Attendance

Incident Type:	Fire
Property Type:	Property/Outdoor/Outdoor structures/Wheelie Bin
Persons Rescued, Extricated, or Killed:	No
Persons Evacuated:	No
Pumping Appliances Deployed Before Mobilising Stopped:	1

Incident Location

Building Name / Number:	
Street:	ROMAN WAY
Town:	WALTHAM ABBEY
Post Code:	

Additional Information

Do Fire Regulations Apply:	No
Cause/Motive:	Accidental
Estimated Fire Damage:	Up to 5
Hazmats Involved:	No

Action



Extract Copy of Fire Report

Damage

Signed:

Ana M Tuckwell | Information Governance Manager & Deputy DPO Systems and Data Department